TABLE 3: DESCRIPTION OF FACILITIES (BUS AND MINIBUS-TAXI ONLY)

NO.	FACILITY NAME	Condition of existing facility	Geometric features
		(e.g. paving lighting, ablution facilities, shelters etc.)	(e.g. size of facility in m² and number of loading bays)
		One shelter provided (see photo). Paved walkway, no	Lay-by (space for three taxi's)
1.	Franschhoek lay-by	additional lighting or ablution facilities provided.	, , , ,
2.	Franscchoek	On Street, no facilities are provided at this location (lighting, shelters and ablution)	N/A: Informal usage of side street (Reservoir Street)
3.	Kayamandi Bridge	Off Street, no paving and no facilities are provided at this location (lighting, shelters and ablution)	N/A: Informal usage of open space adjacent to the bridge.
	, ,	On Street, no facilities are provided at this location	N/A: Informal usage of street (Masitandane Street, Kayamandi)
4.	Kayamandi	(lighting , shelters and ablution)	
		One shelter provided (see photo). Paved walkway, no	Lay-by (space for approximately 15 taxi's)
5.	Sawmills	additional lighting or ablution facilities provided.	
6.	Stellenbosch Station	In existing parking area, no facilities are provided at this location (lighting, shelters and ablution)	N/A: Informal usage of parking lot space adjacent to businesses.
7.	Klapmuts	Off Street, no paving and no facilities are provided at this location (lighting, shelters and ablution)	N/A: Informal usage of open space adjacent to the clinic.
		Paved walkway adjacent to lay-by, no additional lighting	8 lay-bys
8.	Pniel	or ablution facilities provided.	
		Paved surface with formal bays. No additional facilities	Formal space for 40 taxi vehicles on a total area of 2700m ² for
9.	Lanquedoch	however are provided.	the facility.
		Formal taxi rank. All facilities are provided (lighting,	Formal space for 45 taxi vehicles on a total covered area of
10.	Bergzight	ablution and shelter).	1315m ² for the facility.